

## CM 3026

# Crock meter



### Crock meter

Crockmeter testing is used to evaluate the color transfer of a fabric. Generally, a surface of the fabric or textile product is rubbed with a certain pressure and movement on a crockmeter, a standard abrasion (friction) device.

Suitable for testing according to EN ISO standards 105-X12.

#### Accessories (available as optional extras)

- Cotton cloth according to DIN EN ISO/DIS 105-F09.

#### Technical Data

Footprint: 400 × 400 mm

Supply voltage: 230 V

Supply frequency: 50 Hz

Reference N° **CM 3026**

Phone: +49 6331 2490 0, E-Mail: [peter.schultheis@pfi-germany.com](mailto:peter.schultheis@pfi-germany.com)